

Quality Woolfelt



Composition

100% high quality merino
pure new wool

Properties

- Thermal and acoustic insulation properties
- Heat resistance
- Easy care

Maintenance Regular cleaning



Gently use the
vacuum cleaner

or



Gently brush
by hand

Instruction

Regular cleaning

Wool has a low degree in dry soil pick-up. To remove any accumulation of general airborne debris, the wool felt should be vacuum cleaned regular or gently brushed by hand. A slight shedding of the fibers is normal and not indicative of any defect. The loose fibers can be vacuumed away. This process will decrease over the time.

Spot cleaning

As wool contains Lanolin, a waxy coating, the product is „waterproof“. This allows time for liquid spills to be blotted away before permanent staining can occur. Therefore, if a wet spill occurs, blot up the liquid as soon as possible with a dry cloth or paper towels to avoid absorption. Soiled areas may be spot-cleaned with warm water or a mild dry-cleaning solvent. Avoid aggressive rubbing as this can continue the felting-process and change the appearance of the felt. If felt can be removed, obtaining the service of a specialist that is familiar with the special care of wool is recommended.

Spot cleaning



Blot up the liquid
with dry cloth or
paper towels



Use warm water or
a mild dry-cleaning
solvent.

**MAINTENANCE
WOOLFELT**

**Feel free... to ask your questions. To express your interest. To share your ideas.*